

F. Site Reconnaissance

1. Methodology and Limiting Conditions

A site inspection form is included at the end of this report as Appendix D. The inspection form is completed during the non-destructive physical inspection of the PROPERTY to document the Inspector's observations on-site and, to the extent possible, on the adjoining property. The Inspector does not disturb, dismantle or rearrange any materials, containers or equipment in performance of the inspection. Nor does the inspector look under floors, above ceilings, or behind walls.

The representatives of Anderson & Associates, Inc. walked the entire perimeter boundary of the PROPERTY, walked any roads, drives, sidewalks and pathways, and walked an appropriate grid pattern over the remaining area not covered above, including wooded/overgrown areas (where possible), to observe and record evidence of environmental concern. The Inspector took photographs depicting the general overall condition of the PROPERTY and photographed each item of environmental concern observed to document its condition. These photographs are included in Appendix A. The locations of items of concern and/or of photographs taken are delineated on the photo location map in Appendix B.

There were no limiting conditions noted during our site visit with the exception of two locked rooms in the agricultural building. Keys for those rooms were not available at the time of our visit.

2. General Site Setting

See Environmental Site Inspection Form in Appendix D for observations. Significant observations, if any, are noted in Section H, Findings. See Photos in Appendix A.

3. Exterior Observations

See Environmental Site Inspection Form in Appendix D for observations. Significant observations, if any, are noted in Section H, Findings. See Photos in Appendix A.

4. Interior Observations

See Environmental Site Inspection Form in Appendix D for observations. Significant observations, if any, are noted in Section H, Findings. See Photos in Appendix A.