

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VIRGINIA POLYTECHNIC INSTITUTE ST UNIV (Continued)

1000448456

Year: 01
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

Document ID: NYB9480834
Manifest Status: Not reported
Trans1 State ID: PAD146714878
Trans2 State ID: Not reported
Generator Ship Date: 11/13/2001
Trans1 Recv Date: 11/13/2001
Trans2 Recv Date: Not reported
TSD Site Recv Date: 11/14/2001
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: VAD074747908
Trans1 EPA ID: NYD049836679
Trans2 EPA ID: Not reported
TSDF ID: XN37493PA
Waste Code: D008 - LEAD 5.0 MG/L TCLP
Quantity: 03980
Units: P - Pounds
Number of Containers: 001
Container Type: CM - Metal boxes, cases, roll-offs
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 01.00
Year: 01
Manifest Tracking Num: Not reported
Import Ind: Not reported
Export Ind: Not reported
Discr Quantity Ind: Not reported
Discr Type Ind: Not reported
Discr Residue Ind: Not reported
Discr Partial Reject Ind: Not reported
Discr Full Reject Ind: Not reported
Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: Not reported

MAP FINDINGS

Map ID
 Direction
 Distance
 Elevation

Site

Database(s)

EDR ID Number
 EPA ID Number

53
 South
 1/2-1
 0.718 mi.
 3790 ft.

MOORE RESIDENCE
305 DUNTON DRIVE
BLACKSBURG, VA 24060

LUST **S105027975**
LTANKS **N/A**

Relative:
Higher

LUST REG WC:
 Region: WC
Case Status: Not reported
 Date Reported: 1996-10-07 00:00:00
 Date Closed: 1996-12-31 00:00:00
 Release Reported: Not reported
 Pollution Control #: 97-1032N
 Case Manager: Not reported
 Owner Name: Mr. John Moore
 Owner Address: 305 Dunton Drive
 Owner City,St,Zip: Blacksburg, VA 24060
 Owner Phone: -0-

Actual:
2138 ft.

LTANKS:
 CEDS Facility Id: 200000082260
Case Status: Closed
 Pollution Complaint #: 19971032
 Reported: 07-Oct-1996

M54
 SSW
 1/2-1
 0.730 mi.
 3854 ft.

VIRGINIA TECH FOUNDATION RENTAL HOUSE
702 SOUTHGATE DR
BLACKSBURG, VA 24060

LUST **S107999234**
N/A

Site 1 of 3 in cluster M

Relative:
Lower

LUST REG WC:
 Region: WC
Case Status: Closed
 Date Reported: Not reported
 Date Closed: Not reported
 Release Reported: 10/28/05
 Pollution Control #: 20062040
 Case Manager: Robert L Howard
 Owner Name: Not reported
 Owner Address: Not reported
 Owner City,St,Zip: Not reported
 Owner Phone: Not reported

Actual:
2097 ft.

M55
 SSW
 1/2-1
 0.730 mi.
 3854 ft.

VIRGINIA TECH FOUNDATION RENTAL HOUSE
702 SOUTHGATE DR
BLACKSBURG, VA 24060

LTANKS **S107472165**
N/A

Site 2 of 3 in cluster M

Relative:
Lower

LTANKS:
 CEDS Facility Id: 200000222459
Case Status: Closed
 Pollution Complaint #: 20062040
 Reported: 28-Oct-2005

Actual:
2097 ft.

MAP FINDINGS

Map ID
Direction
Distance
Elevation

Site

Database(s)

EDR ID Number
EPA ID Number

M56 **SYDOR RESIDENCE**
SSW **704 SOUTHGATE DR**
1/2-1 **BLACKSBURG, VA 24060**
0.730 mi.
3857 ft. **Site 3 of 3 in cluster M**

LUST **S105990805**
LTANKS **N/A**

Relative:
Lower

LUSTR REG WC:
Region: WC
Case Status: Not reported
Date Reported: 2003-09-10 00:00:00
Date Closed: Not reported
Release Reported: Not reported
Pollution Control #: 04-2022N
Case Manager: Not reported
Owner Name: WILLIAM SYDOR
Owner Address: 704 SOUTHGATE DR.
Owner City,St,Zip: BLACKSBURG, VA 24060
Owner Phone: 540-951-4325

Actual:
2097 ft.

LTANKS:
CEDS Facility Id: 200000212462
Case Status: Closed
Pollution Complaint #: 20042022
Reported: 10-Sep-2003

N57 **208 BARGER STREET RESIDENCE**
WNW **208 BARGER ST**
1/2-1 **BLACKSBURG, VA 24060**
0.738 mi.
3895 ft. **Site 1 of 4 in cluster N**

LUST **S107870095**
LTANKS **N/A**

Relative:
Lower

LUSTR REG WC:
Region: WC
Case Status: Closed
Date Reported: Not reported
Date Closed: Not reported
Release Reported: 2006-02-16
Pollution Control #: 20062063
Case Manager: Robert L Howard
Owner Name: Not reported
Owner Address: Not reported
Owner City,St,Zip: Not reported
Owner Phone: Not reported

Actual:
2083 ft.

LTANKS:
CEDS Facility Id: 200000223298
Case Status: Closed
Pollution Complaint #: 20062063
Reported: 16-Feb-2006

Map ID
 Direction
 Distance
 Elevation

MAP FINDINGS

Site

Database(s) EDR ID Number
 EPA ID Number

N58
WNW
1/2-1
0.739 mi.
3902 ft.

RAYMOND CHISHOLM
206 BARGER ST
BLACKSBURG, VA 24060

Site 2 of 4 in cluster N

LTANKS **U003677982**
UST **N/A**

Relative: LTANKS:
Lower CEDS Facility Id: 200000089125
Case Status: **Closed**
Actual: Pollution Complaint #: 19930407
2083 ft. Reported: 25-Aug-1992

UST:

Facility:

Facility Id: 2026506
 CEDS Facility ID: 200000089125
 Facility Type: UNKNOWN

UST:

Facility Id: 2026506
 Owner Id: 31271
 Owner Name: RAYMOND CHISHOLM
 Owner Address: 203 COLLEGE AVENUE
 Owner Address2: MONTGOMERY
 Owner City, State, Zip: BLACKSBURG, VA 24060
 UST Status: NULL
 AST Status: NULL

Federally Regulated: No

Tank Number: 1
 Tank Capacity: 550
 Tank Contents: HEATING OIL
Tank Status: **PERM OUT OF USE**
 Tank Type: UST

Tank Material:

Tank Type: UST
 Fac Id: 2026506
 Own Id: 31271
 Tank Number: 1
 Install Date: Not reported
 Tank Status: PERM OUT OF USE
 Tank Materials: Bare Steel N
 Tank Materials: Cath Protect Steel N
 Tank Materials: Epoxy Steel N
 Tank Materials: Fiberglass N
 Tank Materials: Concrete N
 Tank Materials: Composite N
 Tank Materials: Double Walled N
 Tank Materials: Lined Interior N
 Tank Materials: Excav Liner N
 Tank Materials: Insulated Tank Jacket N
 Tank Materials: Repaired N
 Tank Materials: Unknown Y
 Tank Materials: Other N
 Tank Materials: Other Note Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RAYMOND CHISHOLM (Continued)

U003677982

Release:

Tank Type:	UST
Fac Id:	2026506
Own Id:	31271
Tank Number:	1
Install Date:	Not reported
Tank Status:	PERM OUT OF USE
Tank Release Detection: Leak Deferred	N
Tank Release Detection: Manual Gauge	N
Tank Release Detection: Autogauge	N
Tank Release Detection: Tank Tightness	N
Tank Release Detection: Vapor Monitor	N
Tank Release Detection: Inventory	N
Tank Release Detection: Stat Invent Recon	N
Tank Release Detection: Spill Install	N
Tank Release Detection: Overfill Install	N
Tank Release Detection: Groundwater	N
Tank Release Det: Int Secondary Containment	N
Tank Release Detection: Int Double Walled	N
Tank Release Detection: Other Method	N
Tank Release Detection: Other Note	Not reported
Pipe Release Detection: Leak Deferred	Not reported
Pipe Release Detection: Autoleak	N
Pipe Release Detection: Line Tightness	N
Pipe Release Detection: Stat Invent Recon	N
Pipe Release Detection: Groundwater	N
Pipe Release Det: Int Secondary Containment	N
Pipe Release Det: Interior Double Walled	N
Pipe Release Detection: Other Method	N
Pipe Release Detection: Other Note	Not reported

Pipe Material:

Tank Type:	UST
Fac Id:	2026506
Own Id:	31271
Tank Number:	1
Install Date:	Not reported
Tank Status:	PERM OUT OF USE
Pipe Type:	UNKNOWN
Pipe Materials: Bare Steel	N
Pipe Materials: Galvanized Steel	N
Pipe Materials: Copper	N
Pipe Materials: Fiberglass	N
Pipe Materials: Cath Protect	N
Pipe Materials: Double Walled	N
Pipe Materials: Secondary Containment	N
Pipe Materials: Repaired	N
Pipe Materials: Unknown	Y
Pipe Materials: Other	N
Pipe Materials: Other Note	Not reported

Tank Number:	2
Tank Capacity:	550
Tank Contents:	HEATING OIL

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RAYMOND CHISHOLM (Continued)

U003677982

Tank Status:	PERM OUT OF USE
Tank Type:	UST
Tank Material:	
Tank Type:	UST
Fac Id:	2026506
Own Id:	31271
Tank Number:	2
Install Date:	Not reported
Tank Status:	PERM OUT OF USE
Tank Materials: Bare Steel	N
Tank Materials: Cath Protect Steel	N
Tank Materials: Epoxy Steel	N
Tank Materials: Fiberglass	N
Tank Materials: Concrete	N
Tank Materials: Composite	N
Tank Materials: Double Walled	N
Tank Materials: Lined Interior	N
Tank Materials: Excav Liner	N
Tank Materials: Insulated Tank Jacket	N
Tank Materials: Repaired	N
Tank Materials: Unknown	Y
Tank Materials: Other	N
Tank Materials: Other Note	Not reported
Release:	
Tank Type:	UST
Fac Id:	2026506
Own Id:	31271
Tank Number:	2
Install Date:	Not reported
Tank Status:	PERM OUT OF USE
Tank Release Detection: Leak Deferred	N
Tank Release Detection: Manual Gauge	N
Tank Release Detection: Autogauge	N
Tank Release Detection: Tank Tightness	N
Tank Release Detection: Vapor Monitor	N
Tank Release Detection: Inventory	N
Tank Release Detection: Stat Invent Recon	N
Tank Release Detection: Spill Install	N
Tank Release Detection: Overfill Install	N
Tank Release Detection: Groundwater	N
Tank Release Det: Int Secondary Containment	N
Tank Release Detection: Int Double Walled	N
Tank Release Detection: Other Method	N
Tank Release Detection: Other Note	Not reported
Pipe Release Detection: Leak Deferred	Not reported
Pipe Release Detection: Autoleak	N
Pipe Release Detection: Line Tightness	N
Pipe Release Detection: Stat Invent Recon	N
Pipe Release Detection: Groundwater	N
Pipe Release Det: Int Secondary Containment	N
Pipe Release Det: Interior Double Walled	N
Pipe Release Detection: Other Method	N
Pipe Release Detection: Other Note	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

RAYMOND CHISHOLM (Continued)

U003677982

Pipe Material:
Tank Type: UST
Fac Id: 2026506
Own Id: 31271
Tank Number: 2
Install Date: Not reported
Tank Status: PERM OUT OF USE
Pipe Type: UNKNOWN
Pipe Materials: Bare Steel N
Pipe Materials: Galvanized Steel N
Pipe Materials: Copper N
Pipe Materials: Fiberglass N
Pipe Materials: Cath Protect N
Pipe Materials: Double Walled N
Pipe Materials: Secondary Containment N
Pipe Materials: Repaired N
Pipe Materials: Unknown Y
Pipe Materials: Other N
Pipe Materials: Other Note Not reported

N59
WNW
1/2-1
0.739 mi.
3902 ft.

206 BARGER STREET ~
206 BARGER STREET
BLACKSBURG, VA

LUST **S105986788**
N/A

Site 3 of 4 in cluster N

Relative:
Lower

LUST REG WC:
Region: WC
Case Status: Not reported
Date Reported: 1992-08-25 00:00:00
Date Closed: Not reported
Release Reported: Not reported
Pollution Control #: 93-0407N
Case Manager: Not reported
Owner Name: RAYMOND CHISHOLM
Owner Address: 203 COLLEGE AVE.
Owner City,St,Zip: BLACKSBURG, VA 24060
Owner Phone: -0-

Actual:
2083 ft.

N60
WNW
1/2-1
0.739 mi.
3902 ft.

207 BARGER STREET RESIDENCE
207 BARGER ST
BLACKSBURG, VA 24060

LUST **S107870102**
LTANKS **N/A**

Site 4 of 4 in cluster N

Relative:
Lower

LUST REG WC:
Region: WC
Case Status: Closed
Date Reported: Not reported
Date Closed: Not reported
Release Reported: 2006-02-16
Pollution Control #: 20062064
Case Manager: Robert L Howard
Owner Name: Not reported
Owner Address: Not reported

Actual:
2083 ft.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

207 BARGER STREET RESIDENCE (Continued)

S107870102

Owner City,St,Zip: Not reported
Owner Phone: Not reported

LTANKS:

CEDS Facility Id: 200000223300
Case Status: Closed
Pollution Complaint #: 20062064
Reported: 16-Feb-2006